

Jewish Synagogue
Northern Cambria, PA

EXTERIOR PHOTOGRAPHS



E1:
Maple Street
Elevation and Front
Entrance
(SouthWest)




E2:
Dogwood
Street
Elevation
(NorthWest)

Jewish Synagogue
Northern Cambria, PA

EX



E3:
Rear Elevation
(NorthEast)



E4:
Side Elevation
(SouthEast)

Jewish Synagogue
Northern Cambria, PA

EXTERIOR PHOTOGRAPHS



E5:
Detail of
Front
Elevation



E6:
Condition
of front
parapet
from rear

Jewish Synagogue
Northern Cambria, PA

EXTERIOR PHOTOGRAPHS



E7:
Cornerstone
Left Side



E8:
Cornerstone
Right Side

Jewish Synagogue
Northern Cambria, PA

INTERIOR PHOTOGRAPHS



I1: View from balcony




I2: View of Balcony and Lobby

INTERIOR PHOTOGRAPHS




13: View from Balcony




14: View of Balcony Seating

INTERIOR PHOTOGRAPHS





15: Stairs from
Balcony going down
toward Lobby



16: View of Front Lobby

INTERIOR PHOTOGRAPHS

17: View of Stairs Up to Balcony
from Front Lobby



18: Stairs from
Lobby going down
toward Basement

Jewish Synagogue
Northern Cambria, PA

INTERIOR PHOTOGRAPHS



19: View from Basement looking back toward stairs